

# DISCIPLINE: Hardware— Switches & Routers

## Discipline Roadmap for: Switches & Routers

DOMAIN: COMMUNICATION SERVICES

Current		2 Years		5 Years	
<b>Baseline Environment</b> <b>Switches</b> 3COM switches 6506 Switch Cisco Switches catalyst (2916, 2924, 4003, 4006, 6513, 3550) DMV Core Switches Nortel Accelar 1150R-B Nortel Switches (350,450) Enterasys		<b>Tactical Deployment</b>  Cisco Nortel Enterasys		<b>Strategic Direction</b>  Market Watch	
<b>Routers</b> 6506 Switch/Router Cisco 4000 Routers Cisco Routers (1650,2500, 2600, 2620, 3660, 3600, 1750, DSL Cisco 840) Nortel ARNs					
				<b>Shared</b> ✓	<b>Agency</b> ✓
<b>Retirement Targets</b>		<b>Mainstream Platforms</b> (must be supported) Cisco, Nortel, Enterasys			
<b>Containment Targets</b> (no new development)  3COM, Avaya, HP			<b>Emerging Platforms</b>		
<b>Implications and Dependencies</b> Only select from products that support industry standards.					
<b>Roadmap Notes</b>					

# **DISCIPLINE: Hardware— Switches & Routers (Cont'd)**

## **Discipline Roadmap for: Switches & Routers**

- **Discipline Boundaries:**

- Equipment room, MDF-IDF equipment. Only wiring closets.

- **Discipline Standards:**

- IETF routing standards.

- **Migration Considerations:**

- TBD

- **Exception Considerations:**

- TBD

- **Miscellaneous Notes:**

- None.

- **Date Last Updated:**

- October 8, 2003

- **Next Review Date:**

- October 8,2004